


CONSTRUCTION DETAILS

1. INSTALL OPTICOM DETECTOR EYE

REVISIONS		APPROVALS	
A	4/94 REPLACE FAILED LOOP DETECTORS AW-676-501-085 AC-STPG-0005(198)E RCS		TEAM LEADER, TRAFFIC ENGINEERING DESIGN DIVISION
B	10/97 EXCLUSIVE W/B AND S/B US 113 E/P LT W/B MD 346 DBD MAR DAZ TH		ASST. CHIEF TRAFFIC ENGINEERING DESIGN DIVISION
C	9/00 INSTALL OPTICOM DETECTOR FOR E/B MD 346		CHIEF, TRAFFIC ENGINEERING DESIGN DIVISION
		DIRECTOR, TRAFFIC & SAFETY	



MARYLAND DOT - STATE HIGHWAY ADMINISTRATION
Office of Traffic & Safety
TRAFFIC ENGINEERING DESIGN DIVISION

US 113 AND MD 346

DRAWN BY: BRUCE THOMPSON	F.A.P. NO.	TS NO.
CHECKED BY:	S.H.A. NO.	1738 C
SCALE: 1"=20'	COUNTY: WORCESTER	
DATE: 7-31-00	LOG MILE: 23011328.88	

T.I.M.S. NO. E-025	SHEET NO. 1 OF 2
--------------------	------------------